



## Autumn update 2022

### Wind turbine blade & rotor recovery

Work to recover the blades and rotor of a wind turbine from the seabed, following an incident late last year during planned maintenance, has been successful.

Debris should now be minimal but the clean up operation team will continue to monitor the surrounding coastline.

### What to do if you find debris:

Do not attempt to remove the debris yourself. Please call 0333 4141 912 to report what you have found and its location. Thank you to everyone who has been in touch with us to date.



### Vattenfall in the UK

We are one of Europe's largest producers and retailers of electricity and heat.

We tackle complex challenges in order to reach our goal of fossil free living within one generation.

Visit our website and discover what we're doing to make our goal a reality.

[www.vattenfall.co.uk](http://www.vattenfall.co.uk)



Recovered wind turbine hub



Examples of debris found on beaches along the coast following the initial incident